## PR001 03-Sep-10

## **Preliminary Report of Accident**

U.S. Department of Labor
Mine Safety and Health Administration

⇎
.,,

1. Accident Type:								11011
	2. Accident Classi	fication		3. Date/Time of	Accident	4. Date/Time of De	eath	5. Fatal Case No
Fatal Injury Powered Haulage				09/03/2010	09/03/2010 01:20 AM 09/03/201		01:20 AM	44
6. Mine Information:								
a) Mining Company Name		b) Mine Name			c	) Parent of Mining (	Company	
Mallards Creek Energy In	ıc	Kansas Mine	•			IATIONAL COAL		MA
7. Mine Location :	a) City	b) (	County	c) State		8. Mine ID Number		9. Union:
Nau	v00	Walker		AL		01-03398		NO
10. Primary Mineral Mined: BITUMINOUS		11. Number of Mine Employees:	a) Total b) 28	Underground	c) Open Pit/	Quarry d) M 28	lill/Prep Plant	e) Other
12. Contractor Name:		<del></del>		······································	13. Uni		14. Contract	tor ID Number:
15. Contractor Address:	a) City		b)	County		c) State	d) Zij	Code
16. Number of Contractor Em	ployees:	a) Total b	) Underground	c) Open 1	Pit/Quarry	d) Mill/Pro	ep Plant	e) Other
17. Number of Persons in Mine	at Time of Assid			T 10 11 1				
	4.4		es: 0	18. Number of		^		•
19) Location of Accident	в	Contractor Employe	es: U	a) Mine Emp	loyees:	0 b) Co	ntractor Empl	
01-Underground	X 03	-Open Pit	07-Advance	Mining	30-Mill/Prep	Plant Othe	er (specify)	20. Mining Height Feet Inches
02-Surface at Undergroun	nd 🔲 06	-Dredge Mining	08-Retreat	Mining	99-Office Fac		(-1)	Feet Inches
21. Nonfatal Injuries:	22. Fata	l Injuries:	<u> </u>		<u> </u>			1 100
23. Victim Information :	a) John F	Name	<u> </u>	b) Age	<u> </u>			<del></del>
c) Regular Job Title:	30111 1		y at Time of Accie	37	<del></del>		- Tall 1.2	
Rock Truck Drive	r	u) Activit	y at Time of Accid	Rock Truck I	Driver		X Mi	ne Employee
24. Experience: Years We	eks Days	Years We	eks Days		Years Week	s Davs		ears Weeks Days
a) Total: 1 50	0 b) а	t the mine: 1 50	) 0 c) at	activity (23d)	1 50	_	Contractor	ours weeks buys
25. Autopsy Performed: NO	If Yes, Location		•			26. Mine Telephor	ne No.: ) 924-8400	
		*	tion in the mine .			<u> </u>	7 324-0400	
27. Description of Accident (inc On September 3, 2010, at another rock truck. The vi bulldozer to clear material. personnel are investigating	approximately ctim had just do It appears the	1:20am, a 37-year Imped and was re	r old rock truck turning to the p	driver was fata bit. The truck ir ed truck and st	Illy injured w	hen the truck he	fore entering	the nit to allow:
On September 3, 2010, at another rock truck. The vi bulldozer to clear material. personnel are investigating	approximately ctim had just do . It appears the g.	1:20am, a 37-year umped and was re victim did not obs	r old rock truck turning to the p serve the stopp	driver was fata bit. The truck in red truck and st	ally injured wan front of him ruck it in the	hen the truck he n had stopped be e rear. MSHA Dis	fore entering strict and Te	g the pit, to allow a chnical Support
On September 3, 2010, at another rock truck. The vi bulldozer to clear material, personnel are investigating.  The information provided in thiregarding the cause of the accidence.	approximately ctim had just do . It appears the g.	1:20am, a 37-year umped and was re victim did not obs	r old rock truck turning to the p serve the stopp	driver was fata bit. The truck in ed truck and st	ally injured wan front of him ruck it in the	hen the truck he n had stopped be e rear. MSHA Dis	fore entering strict and Te	g the pit, to allow a chnical Support
On September 3, 2010, at another rock truck. The vi bulldozer to clear material personnel are investigating.  The information provided in thi regarding the cause of the accid 28. Equipment Manufacturer:	approximately ctim had just do . It appears the g	1:20am, a 37-year umped and was re victim did not obs	r old rock truck turning to the p serve the stopp	driver was fata bit. The truck in sed truck and st represent final de	ally injured we front of him truck it in the eterminations a	hen the truck hen had stopped be rear. MSHA Dis	fore entering strict and Te	g the pit, to allow a chnical Support
On September 3, 2010, at another rock truck. The vi bulldozer to clear material personnel are investigating.  The information provided in thi regarding the cause of the accid 28. Equipment Manufacturer:  C1100 Birming	approximately ctim had just do . It appears the g	1:20am, a 37-year umped and was re victim did not obs	r old rock truck turning to the p serve the stopp	driver was fata bit. The truck in led truck and st represent final de	ally injured we front of him truck it in the eterminations a	hen the truck hen had stopped be rear. MSHA Dis	e of the incident	g the pit, to allow a chnical Support
On September 3, 2010, at another rock truck. The vibulldozer to clear material personnel are investigating.  The information provided in thiregarding the cause of the accid 28. Equipment Manufacturer:	approximately ctim had just do . It appears the g	1:20am, a 37-year umped and was re victim did not obs	r old rock truck turning to the p serve the stopp  NLY and does not  ce:  Besseme  35, MSHA Pers	driver was fata bit. The truck in led truck and st represent final de	ally injured we front of him truck it in the eterminations a	hen the truck hen had stopped be rear. MSHA Dis	e of the incident t Number: 44916	g the pit, to allow a chnical Support
On September 3, 2010, at another rock truck. The vi bulldozer to clear material personnel are investigating.  The information provided in thi regarding the cause of the accid 28. Equipment Manufacturer:  C1100 Birming 34. Accident Investigator:	approximately ctim had just do It appears the J. is notice is based of lent.  Komatsugham	1:20am, a 37-year umped and was re victim did not obs  n preliminary data Of  32. Field Office  7. Name of Preparer a	r old rock truck turning to the p serve the stopp  NLY and does not  ce:  Besseme  35. MSHA Pers Johnny	driver was fata bit. The truck in bed truck and st represent final de er AL on Notified: P. Calhoun	ally injured we front of him truck it in the eterminations a	hen the truck he had stopped be rear. MSHA Dis	e of the incident t Number: 44916	g the pit, to allow a chnical Support